

4/1/2013

**TWIN CAM TENSIONER STOCK REPLACEMENT**

\*\*\*\*\*

2- TIMING CHAIN TENSIONERS	140.00
1- CAM SERVICE GASKET KIT	52.00
1- INNER BEARINGS	46.00
1- OUTER BEARINGS	23.00
1- CHANGE OIL AND FILTER*	55.00
4.0 HOURS LABOR	280.00
	-----
	596.00

**TWIN CAM HYDRAULIC TENSIONER UPDATE**

\*\*\*\*\*

1- CAM SERVICE GASKET KIT	52.00
1- ANDREWS CONVERSION KIT	500.00
1- ANDREWS 12N (STOCK) CAMS	280.00
1- INNER BEARINGS	46.00
1- CHANGE OIL AND FILTER*	55.00
4.0 HOURS LABOR	280.00
	-----
	1213.00

PRICES SUBJECT TO CHANGE

\*-OIL CHANGE USING CONVENTIONAL OIL, ADD \$30.00 FOR SYN3 OIL.